



## ASSEMBLY GUIDE: G2 FOLD LEG

Version 1.0



Installation of the Gocycle G2 Fold Leg



---

## CONTENTS

Overview .....	1
Parts List .....	1
Tool List .....	1
1. Fold Leg Preparation .....	2
2. Fold Leg Installation.....	3




## OVERVIEW

This assembly guide details installation of the G2 Fold Leg. If you have any questions, or require any further assistance, please contact [techsupport@gocycle.com](mailto:techsupport@gocycle.com).

## PARTS LIST

To successfully complete the procedure you will require the following parts:



	Part Code	Part Description	Quantity
A	2132	G2 Fold Leg	1
B	2453	Fold Leg Top Hat	1
C	2454	Pan Head Pozi M3x10	3
D	2456	Wave Spring	2

## TOOL LIST

To successfully complete this procedure you will require the following tools. *You can purchase special KKL tools by their tool number detailed below.*

Part Code	Tool Description
1263	Pozidrive Screwdriver



## 1. FOLD LEG PREPARATION



1.1. Locate the Fold Leg Top Hat (B) and fit the two Wave Springs (D) as shown.

*Note the correct and incorrect alignment of the Wave Springs.*

1.2. Now install the Top hat with wave springs into the G2 Fold Leg (A) as shown.



## 2. FOLD LEG INSTALLATION



**WHEN INVERTING THE GOCYCLE, DO SO ON A SOFT, NON-MARKING SURFACE, E.G. CARPET, TO AVOID DAMAGE TO THE GOCYCLE DASHBOARD DISPLAY**

2.1. For ease, invert the Gocycle so that it rests on its handlebars and saddle. Locate the pivot block feature, indicated.

2.2. Install the Fold Leg and Top Hat as shown. Orientate the Top Hat so the three screw holes align with the pivot block feature.

2.3. Install the three Pan Head Pozi M3x10 (C) screws and use the Pozidrive Screwdriver to fully tighten.



Fold Leg installation complete.

---

**IMPORTANT NOTE: THE ABOVE ASSEMBLY STEPS MUST BE CARRIED OUT IN ORDER.  
FAILING TO DO SO MAY RESULT IN DAMAGE TO THE GOCYCLE.**

---

If you have any further queries or comments, please contact Gocycle Technical Support:

**[techsupport@gocycle.com](mailto:techsupport@gocycle.com)**